



**ISD #381**  
**Lake Superior Schools**  
**William Kelley Addition and Renovation**








**ICS Weekly Progress Report**  
**Friday – February 23, 2024**

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614

## *William Kelley Addition and Renovation*






### **Completed week ending February 23, 2024**

-  Roof flashing at main entrance.
-  Punch list corrections at main entrance.
-  Waterproofing last section of foundation walls at Area B Music Suite
-  Finish backfilling at Area B Music Suite
-  Continued corridor tile work.
-  Continued removal of lockers and wall infills in corridor.
-  Poured back concrete floor in boys' locker room.



### **Upcoming planned work**

-  Structural steel installation at Area B Music Suite
-  Continue corridor tile work.
-  Start wall and ceiling framing floor in boys' locker room.



**ISD #381**  
**Lake Superior Schools**  
**William Kelley Addition and Renovation**

**ICS Weekly Progress Report**  
**Friday – February 23, 2024**

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614

**Progress Photos**



Metal panel reinstallation Area B Music Suite



Backfill and soil grading/compaction Area B Music Suite



**ISD #381**  
**Lake Superior Schools**  
**William Kelley Addition and Renovation**

**ICS Weekly Progress Report**  
**Friday – February 23, 2024**

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614



New concrete floor infills in boys' locker room.



Bull nose tile work in corridors.